

TABLE 2		
LIST OF SOLID WASTE MANAGEMENT UNITS (SWMUs) AND AREA OF CONCERNS (AOCs) REQUIRING CORRECTIVE ACTION		
SWMU/AOC	DESCRIPTION	COMMENTS
18	McGregor Range Rubble Pit Landfill No.13	Inactive since approximately 1983
19	Active McGregor Range Evaporation pond	Active since 1972
20	McGregor Range Open Detonation Area	Inactive since approximately 1960s
25	Orogrande Range Rubble Pit Landfill No.14	Dates of operation: 1950s to 1984
26	Dona Ana Range Open Detonation unit	Dates of operation: 1940s to 1997
27	Dona Ana Range Rubble Pit Landfill No.12	Dates of operation: 1950s to 1984
29	Dona Ana Range Sanitary Landfill No.11	Inactive since approximately 1945

TABLE 3
LIST OF SOLID WASTE MANAGEMENT UNITS (SWMUs) AND AREA OF CONCERNS (AOCs)
NOT CURRENTLY REQUIRING CORRECTIVE ACTION

SWMU/AOC	DESCRIPTION	DATE OF NFA APPROVAL	COMMENTS
21	McGregor Range Fire Training Area	12/15/2004	Inactive since approximately 1983
22	McGregor Range Inactive Waste Drum Storage	12/15/2004	Inactive since approximately 1991
66	McGregor Range Borrow Pit Drum Burial Site	12/15/2004	Date of operation unknown
78	Hueco Range Camp	12/15/2004	Inactive since approximately 1960s

TABLE 4 LIST OF SOLID WASTE MANAGEMENT UNITS (SWMUs) AND AREA OF CONCERNS (AOCs) WHERE CORRECTIVE ACTION IS COMPLETE WITH CONTROLS		
SWMU/AOC	DESCRIPTION	COMMENTS
27B	Active Dona Ana Range Evaporation Pond	Monitoring Required ^{1,2,3}
76	Active Meyer's Small Arms Range Oxidation Pond	Monitoring Required ^{1,2,3}

¹ Monthly monitoring of wastewater influent flow rate required

² Semiannual sampling of wastewater influent for chemical analysis of VOCs by EPA Method 8260, SVOCs by EPA Method 8270 on 8310, and Target Analyte List metals by EPA Methods 6000 and 7000 Series.

³ Groundwater samples to be collected in 2007 and every five years thereafter for analysis as described in item ² above.

TABLE 5
LIST OF HAZARDOUS WASTE MANAGEMENT UNITS

SWMU/AOC	DESCRIPTION	COMMENTS
17	Subpart-X Open Detonation	Undergoing closure