



New Mexico Environment Department
 Surface Water Quality Bureau - Point Source Regulation Section
 2017 CGP NPDES Inspection Reports



Permit / Tracking	Permittee / Operator/ Facility Name	Date
NMR10009D	Abrazo Homes, LLC / Santa Monica Estates, Albuquerque	2017-12-20
NMU001939	Alliance Residential Company/Broadstone Northpoint	2017-08-08
NMU001985	Arista Group LLC, The / Sonoma Ranch East Phase 9	2019-02-13
NMU001957	Banes General Contractors, Inc. / CarMax Auto Superstores West Coast	2018-01-03
NMR1000QP	Bradbury Stamm Construction / Morningstar of Santa Fe	2017-10-25
NMU001931	Caja del Rio Holdings, LLC	2017-03-08
NMR1000NX	Caliper Construction, Inc. / Sonoma Ranch East Phase 9	2019-02-13
NMR1000UC	Carmax Auto Superstores West Coast, Santa Fe	2018-01-03
NMR1000QD	CBKN Dirtworks, Inc. / Southwest New Mexico Regional Landfill	2018-01-17
NMU001947	Confluent Development / CD MS Pacheo LLC	2017-10-25
NMR10012X	D.R. Horton / Enchanted Hills Subdivision	2018-07-19
NMR1002AG	Double M Properties / Legacy at Sierra Vista	2020-12-12
NMU001987	Eichenour, Robert / Canada del Oso Ranch	2019-02-27
NMR1001HE	FacilityBUILD, Inc. / Taos Senior Center	2018-09-20
NMR1000CX	Fortis Construction, Inc. / Project Antelope, Los Lunas	2017-11-01
NMU001984	French Brothers, Inc. / Sonoma Ranch East Phase 9	2019-02-13
NMR1000UH	Gallardo Construction, LLC / Metro Verde South 3A & 3B	2018-05-03
NMR10016Q	Gallardo Construction, LLC / Metro Verde South 3C	2018-05-03
NMR10003H	Gardner Zemke Company / LANL TA-3 Substation	2017-11-28
NMR1000WX	GM Emulsion, LLC / St. Bede's Episcopal Church	2017-12-21
NMR100003	GMD Development NM, LLC / Amador Project	2017-05-12
NMU001949	Greater Kudo LLC / Project Antelope, Los Lunas	2017-11-01
NMR10012V	Green Fox Landscape Supply, LLC	2018-05-02
NMR1001AH	Guzman Construction Solutions LLC / Mirador Subdivision	2018-09-13
NMR1001BP	Hakes Brothers / Hakes Brothers, LLC / Metro Park Village Phase 2	2019-02-13
NMU001969	Hakes Brothers / Hakes Brothers, LLC / Metro Verde South 2C	2018-05-03
NMR1001QY	HBC Construction/ O'Reilly Auto Parts (Coors)	2019-05-21
NMR1000BN	Homewise Inc. / Corazon Santo Subdivision	2017-11-16
NMU001971	HRV Hotel Partners, LLC / Bishops Lodge	2018-05-23
NMR1001DZ	Hutton Exchange Albuquerque (Coors), LLC. / O'Reilly Auto Parts (Coors)	2019-05-21
NMU001941	New Mexico, State of / General Services Department / NM State Police D7 HQ	2017-08-09
NMR10007T	North I-25 Corporate Center LLC / Broadstone Northpoint	2017-08-08
NMU001715	Ojo Caliente Holdings, Inc. / Ojo Caliente Mineral Springs Resort & Spa, Taos County	2017-05-25
NMR12BJ79	Pulte Homes of New Mexico / Las Campanas at Santa	2017-03-16
NMU001940	R&M Construction / NM State Police D7 HQ	2017-08-09



New Mexico Environment Department
 Surface Water Quality Bureau - Point Source Regulation Section
 2017 CGP NPDES Inspection Reports



Permit / Tracking	Permittee / Operator/ Facility Name	Date
NMR100066	Raylee / The Peaks-Mariposa East, Rio Rancho	2018-02-21
NMR100006	Red Mesa Design and Development / Amador Project	2017-05-12
NMU001979	Salazar, Michael / 67B Torres Road, Talpa	2018-09-20
NMR100105	Santa Monica Place Development, LLC	2017-12-20
NMU001982	SBS Construction and Engineering, LLC / Rohan Subdivision	2018-10-23
NMU001981	Senemar, LLC / Rohan Subdivision	2018-10-23
NMR1000UF	Sierra Norte Development, Inc. / Metro Verde South 3A & 3B	2018-05-03
NMR10016R	Sierra Norte Development, Inc. / Metro Verde South 3C	2018-05-03
NMU001945	Skarsgard Construction, LLC / Beckner Road Improvements	2017-09-27
NMR1000NV	Sonoma Ranch East II, LLC / Sonoma Ranch East Phase 9	2019-02-13
NMU001952	St. Bede's Episcopal Church	2017-12-21
NMU001955	Stillbrooke Homes, Inc. / Santa Monica Estates, Albuquerque	2017-12-20
NMR12BP09	Sundance Mechanical / Senior Campus at Caja Del Rio	2017-03-08
NMU001980	Taos, County of / Taos County Senior Center	2018-09-20
NMU001954	Titan Development / Santa Monica Estates, Albuquerque	2017-12-20
NMR10009C	TQM, LLC / Santa Monica Estates, Albuquerque	2017-12-20
NMU001978	Transcor Development Corporation / Mirador Subdivision	2018-09-13
NMU001951	US Army Corps of Engineers / Los Alamos National Laboratory / TA-3 Substation	2017-11-28

NOTE: NMED SWQB Point Source Regulation Section (PSRS) staff conduct National Pollutant Discharge Elimination System (NPDES) compliance inspections on the behalf of the United States Environmental Protection Agency (USEPA). These inspection reports are sent to the USEPA Region 6 in Dallas to determine compliance with the NPDES permitting program in accordance with requirements of the federal Clean Water Act. In addition, USEPA Region 6 maintains a searchable on-line database with Compliance Assurance and Enforcement Documents for New Mexico at <https://www.epa.gov/nm/compliance-assurance-and-enforcement-documents-new-mexico>. **Contact Sarah Holcomb, Program Manager of the Point Source Regulation Section, 505-827-2798** with any questions about NPDES inspections in the State of New Mexico.